

AIA/CES Registered Provider Program Summary



Provider	General Polymers
Program Number	1996-3
Program Title	Prevention/Treatment: Moisture Related Disbondment
Dates and Locations	<ul style="list-style-type: none"> (Ongoing) varied -General Area or Multiple Locations in, United States
Credit Info	1.0000 LU Hours This program has HSW credit
Description	Detailed presentation describing the causes and preventive actions of moisture vapor transmission. Discussion includes slab construction recommendations as well as remediation measures available to treat an existing problem.
Learning Objectives	<ul style="list-style-type: none"> What is Moisture Related Disbondment The different causes and treatment methods of moisture vapor transmission How to prevent Moisture related Disbondment issues Slab construction recommendations to prevent moisture vapor transmission
Formats Given	Seminar
Cost	Free
Content Level	General
Topics Covered	Performance Technology
Point of Contact	Sue Trimpe
Address	145 Caldwell Dr. Cincinnati, OH 45216
Phone	800-543-7694
Fax	513-761-4496
Email	info@generalpolymers.com
Homepage	www.generalpolymers.com

Prevention/Treatment: Moisture Related Disbondment